

<i>opus:/home/ccd/quilt/src/doc</i>			
Directory / File	Author of Document	Description of Directory / File	
FactSheet.odt	R. Leck	Release document for Quilt Version 13 that contains description of Hardware, Software and File System changes.	
Install.odt	R. Leck	Instructions to developer to install all Quilt software components from scratch.	
crossmounting.odt	R. Leck	How to Manually or Automatically cross mount drives for Argos Camera System	
TroubleshootingGuide.odt	R. Leck	Quick guide to common problems while trying to run Quilt.	
PrincetonInstruments		Directory of documents pertaining to Princeton Instruments hardware/software.	
	PVCAM_MATRIX.ods	Princeton Instruments	Interoperability of Princeton Instruments Controller firmware and host libraries. This spreadsheet shows what version of controller firmware are compatible with the pvcam library releases.
	micromax512BFT.pdf	Princeton Instruments	Micromax 512BFT Operators Manual
	pvcam2.7.pdf	Princeton Instruments	PVCam Version 2.7 API Library Reference
From 12.05 release		Documents from release 12.05 of Quilt	
	help.txt	E. Nather	Functional description of Quilt components
	inside.txt	E. Nather	More detailed functional breakdown of quilt operation
	ntp.txt	E. Nather	Network Time Protocol daemon description
	profile.txt	E. Nather	Template for 'profile' file information
	qmap.txt	E. Nather	Flat Field Compensation explanation
	restart.txt	E. Nather	Snippet of code showing a restart
	usingq12.txt	E. Nather	User instructions based on key presses
manuals			
	Argos-q13.pdf	E. Robinson	PDF version of operations manual for Argos/Quilt detailing setup, usage, reference and troubleshooting. Covers data acquisition and data extraction.
	Argos-WhiteDwarfPulsations.p	Fergal Mullally, Dean Chandler, JJ Hermes	PDF users manual for operating Argos camera and running data acquisition, data extraction and data archival for observing WhiteDwarf Pulsations.
	old		Archive of older manuals from Quilt 12.05

* Directory names in Bold type